

POOL
MODELS: 5100 THRU 6100 HEAT PUMP

CATALOG NO. 9100.78
Effective: 03-29-12
Replaces: 11-05-10

RAYPAK ILLUSTRATED PARTS LIST

MODEL SIZE: 5100, 6100 & 5100ti
MODEL TYPE: HEAT PUMP POOL HEATER
DATES OF MANUFACTURE: 11-04 THRU 9-08


THE PARTS LISTED ARE FOR STANDARD EQUIPMENT FOR THIS MODEL TYPE. RAYPAK RESERVES THE RIGHT TO SUBSTITUTE, DELETE OR CHANGE ANY PART WITHOUT NOTIFICATION. THE ADDITION OF OPTIONS MAY ALSO CHANGE SOME OF THE PARTS. ORDER REPLACEMENT PARTS FROM ACTUAL HEATER COMPONENTS.





FOR DETAILED INSTRUCTIONS, SEE "HOW TO USE YOUR ILLUSTRATED PARTS LIST",
CATALOG NO. 9001.10



Raypak, Inc., 2151 Eastman Avenue, Oxnard, CA 93030
(805) 278-5300 Fax (800) 872-9725
Litho In U.S.A.



* SHEET METAL SHOWN
FOR REFERENCE ONLY
NOT AVAILABLE FOR REPLACEMENT



CALLOUT	DESCRIPTION	5100	6100	5100 ti
	CONTROLS			
1-C	TX Valve	H000007	H000007	H000007
2-C	High Pressure Switch	H000015	H000015	H000015
3-C	Low Pressure Switch	H000013	H000013	H000013
4-C	Temperature Sensor	H000031	H000031	H000031
	HEAT TRANSFER			
1-H	Evaporator Coil	H000071	H000142	H000142
2-H	Heat Exchanger	H000122	H000122	H000122
3-H	Bypass Assembly	H000169	H000042	H000042
4-H	PVC Union	H000055	H000055	H000055
5-H	Liquid Line Drier	H000011	H000011	H000011
6-H	Compressor	H000137	H000137	H000137
	FAN			
1-F	Fan Motor	H000083	H000083	H000083
2-F	Fan Blade	H000123	H000121	H000121
	CONTROL BOX			
1-J	Fan Relay	H000017	H000017	H000017
2-J	Transformer	H000023	H000023	H000023
3-J	Water Pressure Switch	H000025	H000025	H000025
4-J	Contactora	H000043	H000043	H000043
5-J	Capacitor	H000049	H000049	H000049
6-J	Fuse	H000001	H000001	H000001
7-J	Defrost Control Switch	H000065	H000065	H000065
8-J	Control Board	H000035	H000035	H000035
9-J	Delay on Break Timer	H000019	H000019	H000019
10-J	Green LED	H000037	H000037	H000037
11-J	Amber LED	H000039	H000039	H000039
12-J	Knob	H000008	H000008	H000008
13-J	Potentiometer	H000061	H000061	H000061
14-J	Rotary Switch	H000057	H000057	H000057
	MISCELLANEOUS			
1-M	Touch-up Paint			
	Raypak	750125	750125	750125
	Rheem	750251	750251	750251

NOTE: These are R-22 models - R-410A components are not compatible